

Section 1: Salt Spreader Installation:

Step 1: Remove rear mounting 1/2" bolts (4).

Step 2: Line 4 hole bolt pattern up with D-6298 and D-6298 spreader mounting angle brackets..

Step 3: Install bolts through spreader to mount, leave hardware loose until all are in place then tighten. Figure B.

Step 4: Refer to spreader owners manual for operation instructions.

This hitch/mount has been designed to be as universal as possible in regards to fitting a wide variety of skid steer type machines. As with any attachment, practice safe usage and care when installing and operating this equipment. Refer to the owners manual for all warning and safety precautions before using. If you should have any questions or concerns before using, contact your local dealer for further information.

